

PIDS

AUG 10 1965

99710-6

NPIC PROJECT NO.

S E C R E T

CLASSIFICATION

RESPONSIBLE COMPONENT

RECEIPT RB/OS

SUPPORT/SERVICE REQUIREMENT

DISSEMINATED RB/OS

(The following info is required when rqmts are levied by external organizations)

OFFICE \_\_\_\_\_ DATE OF RQMT \_\_\_\_\_ CONTROL NO. \_\_\_\_\_

NPIC DIV/DETACH PROCESSING RQMT \_\_\_\_\_ PROJ OFF \_\_\_\_\_ PHONE \_\_\_\_\_

SUPPORT REQUESTED OF \_\_\_\_\_ PRIORITY \_\_\_\_\_ DATE REQUIRED \_\_\_\_\_

(The following info is required when rqmts are levied for internal support)

DIV/STAFF \_\_\_\_\_ P&amp;DS \_\_\_\_\_ DATE OF RQMT 6 August 1965 \_\_\_\_\_ CONTROL NO. \_\_\_\_\_

SUPPORT REQUESTED OF \_\_\_\_\_ P&amp;DS \_\_\_\_\_ PROJ OFF \_\_\_\_\_ PHONE \_\_\_\_\_

PRIORITY \_\_\_\_\_ DATE REQUIRED 1 February 1965 \_\_\_\_\_

25X1

## 1. BACKGROUND INFORMATION:

- The work requested is in support of a Departmental/NPIC : Photo interpretation proj.;
- ☒ Non-photo interpretation project. It will result in: Hard copy report;
- ☐ Informal report (memo); ☒ Basic service only.

Project Description: MEASURING EYEPiece

2. SPECIFIC SUPPORT/SERVICE REQUESTED: Support from NPIC will probably consist of:
- Photographic; Reproduction; Mensuration; Graphics; ADP; Editing;
- ☒ Other (explain below) -- (Include statement as to estimated amount of work required of support component(s); i.e., number of contact prints, enlargements, boards, etc.)

Investigate feasibility of measuring eyepieces for possible use by interpreters on the ☐ Dynazoom high power stereoviewers (per request of IAD/CIA).

25X1

3. URGENCY JUSTIFICATION: (If immediate support is required a statement of justification must be made on this form.)

DATE OF COMPLETION \_\_\_\_\_

S E C R E T

CLASSIFICATION

NPIC FM 218 (Revised 5-65)

NGA Review Complete

25X1